		47-PA 700-PA (PA)		CLAS	SIFICATION	G.	ONFIDENTIÀ	L 🔔	1000141C
			•.				ENCE AGEN		
· .				I	NFORM	OITAN	N REPO	DRT	
	COL	JNTRY	China						DATE DISTR. 2 5050 1954
0X1	SUE	BJECT	Dairen	s Indus	trial Ins	tallation	3		NO. OF PAGES 7
50X1	PLA:	CE UIRED							NO. OF ENCLS.
, ,	DAT	E							(LISTED BELOW) SUPPLEMENT TO
X1			BY SOUR FORMATION						REPORT NO
		OF IN	ONMATION		AND THE PARTY				50X1
	SOL	JRCE	I.S. CODE, AS AMITENTS TO OR REC.	ENDED, ITS TO EIPT BY AN UNI TION OF THIS P	RAMSHISSION OR READVINER PROPERTY OF THE PROPE	cvr- k is	THI 	S IS UN	EVALUATED INFORMATION
	50X	K1							
	1.	Mu and	ware to t	-ha wawa					
		TAY CALTED							
		are gi	ven below	we vari	ous quest	710HB OH B.	pecific in	austria,	t installations in Dairer
	2.	are gr	∧eπ pero#	7.	k Company		pecific in	dustria,	installations in Dairer
50X	2 . K1	are gr	∧eπ pero#	7.		r			i installations in Dairen
50× 50> 50>	2 . K1 K1	Manchu In the map ti Departs	ria Rolli area ind tled "Kwa	icated Intung Late, Di	k Company by the ma eased Ter ivision o	the plant to the p	ant of the	subject Idential ren",	company was not situate
50>	2 . K1 K1	Manchu In the map ti Departs	ria Rolli area ind tled "Kwa	icated Intung Late, Di	k Company by the ma eased Ter ivision o	the plant to the p	ant of the o me /Conf: ty of Dai;	subject Idential ren",	company was not situate formerly Restricted cography. The following
50>	2 . K1 K1	Manchu In the map ti Departs	ria Rolli area ind tled "Kwa	icated Intung Late, Di	k Company by the ma eased Ter ivision o	the plant to the p	ant of the o me /Conf: ty of Dai;	subject idential ren", [and Cart	c company was not situate formerly Restricted cography. The following 50X1
50>	2 . K1 K1	Manchu In the map ti Departs	ria Rolli area ind tled "Kwa ment of S	icated Intung Late, Di	by the ma eased Ter ivision o the area	the plant to the p	ant of the o me Confi ty of Dair tligence a	subject idential ren", and Cart :	company was not situateformerly Restricted cography. The following 50X1
50>	2 . K1 K1	in the map ti Departirough	ria Rolli area ind tled "Kwa ment of S	icated intung Late, Didicates -Ho-K'ou Statio	by the ma eased Ter ivision o the area	the plant to the p	ant of the o me /Confity of Dair elligence actually was:	subject idential ren", and Cart cerpa cerpa e box	company was not situate formerly Restricted cography. The following 50X1
50>	2 . K1 K1	in the map ti Departirough	ria Rolli area ind tled "Kwa ment of S sketch in	icated intung Late, Didicates -Ho-K'ou Statio	by the ma eased Ter ivision o the area	the plant to the p	ant of the o me /Gonfity of Dair alligence actually was:	subject idential ren", and Cart cerpa cerpa e box	company was not situate formerly Restricted cography. The following 50X1
50>	2. K1 X1 X1	In the map ti Departs rough	area ind tled "Kwa ment of S sketch in Sha- ire stati	icated intung Litate, Didicates -Ho-K'ou Statio	by the mate eased Terrivision of the area	the plant of the p	Railroad Polic Stree car line rm side of	subject idential ren", and Cart coverpa e box tear	company was not situateformerly Restricted cography. The following 50X1 N ss was built through a deep
50>	2. K1 X1 X1	in the map ti Departs rough for the strastone of March 1 block s	area ind tled "Kwa ment of S sketch in Sha- ire stati meet on the ut, about 952, but hown in	icated intung Litate, Didicates Ho-K'ou Station he sketce the westhe above	by the mate eased Terrivision of the area on the area of the area	the plane shown to rritory, Confidence as it act the street. The easter had been the nor	Railroad Polic Car line rn side of cut down thern side	subject idential ren", and Cart coverpa e box tcar on it, the cu during '	company was not situateformerly Restricted cography. The following 50X1 N ss was built through a deep t still existed as of World War II, leaving the s block also had a steen
50>	2. K1 X1 X1 X1	in the map ti Departs rough a stone of March I block a cut, who block we have the stone of the s	area ind tled "Kwa ment of S sketch in Sha- ire stati teet on th ut, about 952, but hown in ich faced as unoccu	icated intung Late, Didicates -Hc-K'ou Statio to 50 fee the westhe above in the Shaped in the Shap	by the mate eased Terrivision of the area	the plant shown to ritory, Confident for the first as it act the street. The easter had been the nor a (Sakako)	Railroad Polic Stree car line rn side of cut down thern side railway s	subject idential ren", and Cart coverpa e box tcar on it, the cu during v of this tation.	was built through a deep t still existed as of world War II, leaving the block also had a steep In any event, the whole
50> 50>	2. K1 X1 X1 X1	in the map ti Departs rough : The str stone commarch lock scut, who block warretucture.	area ind tled "Kwa ment of S sketch in Sha- ire stati reet on th out, about 952, but hown in the ich faced as unoccure visibl I would	icated intung Litate, Didicates -Hc-K'ou Statio to 50 fee the westhe above in the Shapied Le was a	by the mate eased Terrivision of the area	the plant shown to ritory, Confident for the first as it act the street. The easter had been the nor (Sakako) ire statio	Railroad Polic Stree car line rn side of cut down thern side n located	subject idential ren", and Cart coverpa e box tcar on it, the cu during v of this tation.	was built through a deep t still existed as of World War II, leaving the shock also had a steep In any event, the whole
50> 50>	2. K1 X1 X1 X1	in the map ti Departs rough a structure of the structure	area ind tled "Kwa ment of S sketch in Sha- ire stati reet on th nut, about 952, but hown in ich faced as unoccu re visibl I would ook.	icated intung Litate, Didicates -Hc-K'ou Statio to 50 fee the westhe above in the Shapied Le was a	by the mate eased Terrivision of the area	the plant shown to ritory, Confident for the first as it act the street. The easter had been the nor (Sakako) ire statio	Railroad Polic Stree car line rn side of cut down thern side railway s n located impossible	subject idential ren", and Cart coverpa e box tcar on it, the cu during v of this tation.	was built through a deep t still existed as of World War II, leaving the solock also had a steep In any event, the whole and the only the western edge of the

SEE LAST PLOT YOU AS RECY & AREA CODES

50X

CONFIDENTIAL

- 2 -

(a) 50X1	As far as I know, railway rolling stock was produced in Dairen prior to 1945 in two plantsthe Southern Manchurian Railway workshops and Dairen Kikai. As far as the railway workshops were concerned, this type of production had been engaged in for a long time. I remember being in the workshops and seeing rolling stock being constructed. Dairen Kikai, on the other hand, was a comparatively new plant and one which was quickly expanding. During
	World War II, I noticed that freight cars were being built there. After the surrender in 1945, I visited the premises and saw rows of unfinished railway
50X1	cars-boxcars and 50-ton gondola cars. The gondola cars were still standing there These cars were not completed, 50X1
	but were intact. I heard that for 1952 the former Southern Manchurian Railway workshops were ordered to produce several hundred freight cars. As regards Dairen Kikai, that section which was formerly engaged in manufacturing rolling
	stock now belongs to Factory No 18. conversations were held 50X1 about recommencing railway car production. Officials of No 18 insisted that they would not have adequate space for such activity and were attempting to annex some territory from Machine Factory No 17. It was the southern part of No 17's territory that was in question. I believe that this thought of reconstituting railway car production may force the unification of Factories No 17 and 18. The whole question illustrates how weak Chinese administrators are in calculating production, because, in Japanese times, Dairen Kikai produced rolling stock in addition to many other items and did not need the space required by Factory No 18.

- (b) A possible theory in regard to the Manchuria Rolling Stock Company is that it might have been a subsidiary of Dairen Kikai. The Japanese in Manchuria usually employed this method of developing new branches in industry and commerce.
- 2. The former Oki Communication Apparatus Manufacturing Company, the former Koka Communications Equipment Manufacturing Company, and the former Toba Iron Works-I have no knowledge of any of these firms, nor any information about airplane assembly work. However, the following thoughts, I believe are pertinent. They represent only reasoning and not definite knowledge. The administration of the electric power complex in Dairen (later known as DALENERGO) was set up by the Soviets very soon after the Japanese surrender and was headed by electrical engineers. These specialists naturally paid most attention to any kind of production connected with electricity. They gathered every type of production facility available in this field and reinforced it with machinery from the USSR. DALENERGO had an electric motor-building shop, which also produced some appliances and did any kind of needed electric repair work. The shop had approximately 400 workmen. This means that the above-mentioned plants were either used by DALENERGO as the basis for this shop, or they had been completely destroyed and their machinery lost or taken piecemed by other plants. Had the factories in question existed intact in 1945, they could not have been overlooked by DALENERGO.
- 3. The former Nishinwa Iron Works (in Kanchingtzu) I have no information about this plant or the former Shinwa Steel Company. However, if one of them was situated in Kanchingtzu, it is very possible that one or both subsequently became Factory No 19 or 20. Factory No 19 or 20 was the plant which produced steel for tools and came under the jurisdiction of the machine building department (or mechanical industry department) in Mukden. I was never at this plant and do not know whether its number was 19 or 20. All that I know about the factory was reported by me in previous interviews.
- 4. The Kuang-ho Machinery Plant I assume that this plant is now under Factory No 19 or Factory No 20 and that its specialty is the manufacture of boilers. The numbered factory, I believe, now produces steam rollers. Another possible theory is that the Kuang-ho Machinery Plant is the former Dairen Boiler Manufacturing Plant, the name of which is mentioned in one of the other questions put to me. I never visited any of these plants.

	50X1
CONFIDENTIAL	· ·
- 3 -	

- 5. In regard to identifying by former name Machine Factory No 18 and Machine Factory

 No 8,

 No 18 is the eastern part of the former

 Dairen Kikai. The northeast corner of these premises should be excepted, because
 here are located the oxygen plant and the tool shop, both of which belong to No 17.

 Factory No 8, if it existed in Dairen, must belong to some other department than that of
 machine building. The only plants which belonged to this department in Dairen were

 Nos 17, 18, 19, and 20.
 - 6. The Tractor Factory The question states that this factory was located four kilometers southwest of the Amanagawa power station. In fact, however, the area two kilometers and more south from this power station consisted only of an open, steep hill with some sort of an artillery battery stationed on top of it, of the race course, and of a settlement called the "doctor's village" (doktorski poselok). The settlement now houses pilots and other airmen. Even further from the power station, a yard for the construction of wooden schooners was built in 1944-45. However, up to the Japanese surrender in 1945, this yard had not turned out any finished production.
 - (a) However, the former Dairen Kikai had engaged in major overhauling of tractors.

 50X1


 caterpillar tracks for tractors as well as some tractor bodies were stored in the yard of the oxygen plant. This activity had not been a major one. It had utilized only two aisles—each approximately only 40 meters long with heavy bridge cranes. The cranes were removed by the Soviets in 1945.
 - (b) Another possible place where tractors had formerly been manufactured was a shop later occupied by the welding department of Machine Factory No 17. This, at least, was the theory of the engineers of No 17. Actually, of course, we did not know for exactly what type of production this shop had previously been used, but its heavy columns spaced close together, its heavy under-rail bars for cranes, and its narrow aisles supported the theory that it had been used for the assembly of tractors. Of course, all this refers to past activity. After World War II believe that no work was being done on tractors.
 - (c) However, by chance I know that ______ the Chinese authorities had organized a tractor repair shop located, I believe, somewhere near the glass factory (see above-mentioned map). The shop was operated by Chinese convict labor. I think that this shop would probably tend to grow and it could become a tractor manufacturing plant.
- In regard to the question about what former companies were consolidated in Dairen since 1945 and what the resulting companies were called, 50X1 at least as far as mechanical works only are concerned. The following summary, however, may be of use in consolidating and clarifying this 50X1 subject. As of 1951-52 in Dairen, the machine industry included the following main plants: the four factories under the northeastern industrial administration in Mukden were Machine Factories No 17 through 20; the Chinese Changchun Railway workshops at Sha-Ho-K'ou; Daldock in Dairen; as well as the navy dock in Port Arthur. The railway workshops had some subsidiary plants such as the Signal Plant near Factory No 18 and the shops of the Dairen Railway District. In addition to the above, there were repair departments or shops at each large plant, such as the cement plant near Shu-Shu-Tzu and the chemical plants in Kanchingtzu. Some of these repair shops had expanded beyond the needs of their individual plants. For example, Vegetable Oil Plant No 2, which incidentally used the hydrogenization process, had set up its repair shop in such a manner and to such an extent (using over 100 workmen) that the shop produced, in addition to its normal activities, water valves of from three to six inches in diameter, and other similar fittings for water works, and even had its own casting department. As a result, 50X1 the officials of the repair shop were anxious to obtain new orders.

	CONFIDENTIAL
	CONFIDENTIAL
	- 4 -
50X1	a large (by Dairen standards) radial drilling machine with a
	radius of over one meter, of Japanese manufacture. This machine apparently was
•	in excess of the needs of the oil plant and even in excess of the needs of its enlarged repair shop. Also the UKS (Upravlenie Kapitalnovo Stroitelstva -
	administration of major construction) of DALENERGO, which concerned itself with
	constructing new buildings for new investments, up to 1951 had set up a shop employing three to four hundred workmen. It had welding, mechanical, fitting,
50X1	and wood-working departments. It also possibly had a small costing
	department. This shop, like most of the other activities of HKS after DALENERGO
50X1	was transferred to a new Chinese building organization which came
	the above data, the situation was as follows:
	(a) The former Southern Manchuria Railway works and its subsidiaries in general
	(a) The former Southern Manchuria Railway works and its subsidiaries in general, no change, although it may have absorbed some neighboring plants.
	(b) Daldockin 1951-52 absorbed one or two small shipyards
	(c) Machine Factory No 17the former Suzuki plant which absorbed some other plants (see the following paragraph for further details).
	(d) Machine Factory No 18the main part of the former Dairen Kikai.
50X1	(e) Nos 19 and 20former Japanese plants
50X1	no additional mechanical plants employing over 50 or 60 work-
50X1	
	best equipment was removed to the ugg rational and disappeared in 1945-46. The
	dispersed among other factories supported by the Soviet authorities and among private Chinese shops. This last means of dispersed
	Chinese shops. This last means of dispersal was very often achieved by plundering.
	Early in 1952 most of the machinery from the private Chinese shops was removed to government-owned plants. Part of this equipment was not used, at least at that time.
8.	In regard to the service.
50X1	In regard to the question as to what companies were absorbed into Machine Plant No 17,
50X1	ful to consolidate it below. Machine Factory No 17, ie, the former "Mechanicheski Zavod DALENERGO" (Machine Factory of DALENERGO) and the former "Mechanicheski"
50X1	Zavod DALENERGO" (Machine Factory of DALENERGO) was composed of:
	(a) The former Suzuki Pipe Plant which had been located at Hiyoshi Cho No 2 in "New Chinatown" during the period 1945-48 to before the
	Chinatown" during the period 1945-48, ie, before this factory amalgamated with
	others to form No 17. This plant did not receive any new equipment during
	(b) The "Instrumentalni Zavod DALEWEDGOV (c
50X1	DALENERGO) was located on the southern book of the southern book of
50X1	tramcar bridge and the street bridge.
50X1	during the period 1945-48 much machinery from other plants had been accumulated on the grounds of this factory. Most of the machinery had been accumulated
50X1	on the grounds of this factory. Most of the machinery was then not in use and
50X1	gave an impression of disorder. The rough sketch below indicates the relative
50X1	positions of Machine Factories No 17 and 18 along with the location of the test

Declassified in Part - Sanitized Copy Approved for Release @ 50-Yr2013/04/30 : CIA-RDP82-00047R000400480002-2

CONFIDENTIAL

positions of Machine Factories No 17 and 18 along with the location of the tool, oxygen, and wood-working shops. See reference map for indication of location in Dairen of the two machine factories.



plants also took over part of the ajoining premises of the switch plant of the Southern Manchurian Railway, and the completely devastated premises of a coal briquette plant and two other plants

(e) In 1948 and early in 1949, after the charmant and the complete state of the switch plant of the briquette plant and two other plants

(e) In 1948 and early in 1949, after the above plants had moved to their new

1000 location, Machine Factory No 17 received much machinery.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO. The latter indicates that machinery had been assembled at other plants belonging to DALENERGO.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO.

1000 part of them were bought from private Chinese owners and some were furnished by DALENERGO.

1000 part of them were bought from private Chinese owners and some were plants belonging to DALENERGO.

1000 part of them were bought from private Chinese owners and some were plants belonging to DALENERGO.

50X1

50X1

the stock of machinery of the Instrument Plant and rehabilitated. In brief, over 100 machines were stored, not covered, on the premises. From 10 to 20% of them were rehabilitated and put into production during the period 1948-51. In 1949-50, Factory No 17 received some new machinery from the USSR.

50X

CONTRA	CTS TOWN	77 A T
CONTRI	I I MANAGE	. דמ דייו

6

	그는 일이 나는 점점 하는 학생의 사람들은 것이 하는 것이 하고 있다면 하는 것이 하는 것이 되었다면 하는 것이다.
10.	
50X1	Perhang Company,
50X1	was an abbreviated means of reference to "Doing Deals Town W. 1. "
50X1	Shipbuilding Company. The last mentioned firm received "Daldock", je Dairen Dock
50X1	
50X1	"Sino Soviet Shipbuilding Company". Perhaps it includes the word "repairs" as well as "shipbuilding". During the time Daldock was under Soviet management only,
50X1	these two departments were very close to each other and the repair. The premises of
	upon the type of work, ie, repair or ship construction, not on territory. As I understand it, the new Sino Soviet Shippulding Company and a
1.64	prise was unable to contribute anything of nonticular anything of no
50X1	to equipment, buildings, nor people. This amalgamation which formed the new Sino Soviet Shipbuilding Company was carried out merely to satisfy the Chinese and not for any businesslike reasons.
11.	In discussing the question of what non-marine manufacturing is done by the Sino
50X1	Soviet Shipbuilding Company,
50X1	filling some orders over and show the Daldock had the capability of
50X1	filling some orders over and above its marine program and the capability of this capability was fairly sizeable. For example, in the fall of 1950 they agreed to the request of Factory No. 17 that the fall of 1950 they agreed
50X1	
50X1	was put upon the dock by the Soviet Consulate and by Soviet Army suthersities
50X1	
50X1	facture. This is similar to the attitude the railway shops of Dairen, which also were very reluctant to manufacture items not directly connected with railway production.
50X1	directly connected with railway production.
12.	In regard to the question as to what organs of government control each industry,
50X1	VIV VISCULTABLIUM LUBIT CAME INTO OTTOOT OFF ALL
50X1	and Sino Soviet trusts was abolished. in northeastern China in Mukden has special departments (otdeli) for each kind of industry, such as those of machine hudden.
50X1	
50X1	
50X1	The accust degree of influence of these local
50X1	depends upon the relative power, ability, and activity of the from Mukden, there is also a relitical accordance of onese local plant management. In addition to this direct organizational line of control
50X1	from Mukden, there is also a political connection, ie, the Communist Party in Dairen has the power to check on local work.
15.	On the subject of what is left of the system of Soviet and Chinese trusts
	none of the share and a state of the state o
	destroyed after the system of Soviet and Sino Soviet trusts was abolished and the factories came under the jurisdiction of the Chinese northeastern government. Of course the offices of trusts were closed or transformed and
	(even those with small technical shops) such as godown services, supply departments for workers, and housing departments, disappeared completely. In general, industry was represented according to the Soviet method, ie, plants with similar specialties were united under one pertinent department in Mukden, if those plants were large enough, organization followed the Soviet pattern in that all industry was divided into three groups: (a) of all-Union importance
	(b) of Republic importance (c) of local importance

CONFIDENTIAL

-7-

I understand, however, that two activities were not made to fit into this pattern in Dairen in 1952. These were Daldock and the Port of Dairen. I believe that the Soviets are likely to maintain strong influence longest in Daldock. They would do this because they need the work it can do in ship repairing, particularly for Arctic voyages, so long as the Soviets have not developed extensively dock yards in Vladivostok or in other localities such as Komsomolsk or Nikolaev on the Amur. I cannot recall more specifically, nor did I even know

50X1

50X1

how industrial plants were divided among the various industrial departments in Mukden. As a result I cannot say just to what department each plant was assigned and what new names were given to the plants at that time.

end

LIBRARY SUBJECT & AREA CODES

743 · 33 744 · 7 441L/C 441L/C 441L/C 740.1 741.18 441L/C 743,**28**1 441L/C 441L/C 740.02 740.03 740.09 741 441L/C